





System 1500 Rainscreen Attachment System Details with Polyisocyanurate Insulation

Revised 11/2020






DETAIL:

2

SYSTEM 1500 RAINSCREEN SYSTEM

VERTICAL JOINT




DETAIL:

3

SYSTEM 1500

RAINSCREEN SYSTEM

BASE DETAIL




DETAIL:


4


SYSTEM 1500


RAINSCREEN SYSTEM

WINDOW SILL DETAIL










DETAIL:


SYSTEM 1500



RAINSCREEN SYSTEM


8


METAL COMPOSITE MATERIAL COPING DETAIL
















DETAIL:


13


SYSTEM 1500 RAINSCREEN SYSTEM

JAMB AT EXPANSION JOINT









DETAIL:

16A

SYSTEM 1500

RAINSCREEN SYSTEM

SKYWARD FACING JOINT- HARD FASTENED

